

Scan report date
31/08/2024 12:28

Vehicle registration

Vehicle owner


Device

Location

Location Phone

Recommendations

- Uneven profile on the front left tyre. Please check wheel alignment.
- Rear left tyre is approaching the recommended wear limit of 3.0mm (4.1mm)
- Uneven profile on the rear left tyre. Please check wheel alignment.
- Replace the rear right tyre (2.1mm)
- Uneven profile on the rear right tyre. Please check wheel alignment.




Click on a tread rating to view full history

Normal 5.0mm or higher	Warning Between 3.0mm and 5.0mm	Dangerous 3.0mm or below
----------------------------------	---	------------------------------------

The legal limit for a tyre's tread depth is **1.6mm**

Stopping distance

Based on most worn tyre fitted to all positions, when travelling in wet conditions at 50mph:



Measured tread comparison

